



VP Engineering
 NINGBO MASTER SOKEN ELECTRICAL CO LTD
 NO.19 ZONG YAN RD
 INDUSTRY ZONE
 XIKOU
 NINGBO
 ZHEJIANG 315502 CHINA

Date: 2015/04/02
 Subscriber: 148661001
 PartySite: 570327
 File No: E218957
 Project No: 4786644850
 PD No: 15M14079
 Type: R
 PO Number:

Subject: **Procedure And/Or Report Material**

The following material resulting from the investigation under the above numbers is enclosed.

| <u>Date</u> | <u>Vol</u> | <u>Sec</u> | <u>Pages</u> | <u>Revised Date</u> |
|-------------|------------|------------|--------------------------------------|---------------------|
| | 2 | | Index Page(s) | |
| | 2 | | Revised Appendix FSS | 2015/03/29 |
| | 2 | | Revised Section General Page(s) 5,7 | 2015/03/29 |
| 2014/09/26 | 2 | 1 | Test Record | |
| 2014/09/27 | 2 | 2 | Test Record | |
| 2015/03/29 | 2 | 3 | Description Page(s) | |
| 2015/03/29 | 2 | 3 | New Figure(s) 3 New PhotoDNA | 2015/03/29 |
| 2015/03/29 | 2 | 3 | New Illustration(s) 3 New DrawingDNA | 2015/03/29 |

Please retrieve the documents via MyHome@CDA.

Inspections at your plant will be conducted under the supervision of CHUANGQI LOU, UL INSPECTION CENTER HANGZHOU, CHINA NAT'L IMPORT & EXP COM INSP CORP, YAOJIANG DEVELOPING CENTER, 9TH FL, 305 HUANCHENG NORTH RD, HANGZHOU, ZHEJIANG, China, 310012., PHONE: +86-571-8578-6148, EMAIL: hzic@ccciczhejiang.com

Please file revised pages and illustrations in place of material of like identity. New material should be filed in its proper numerical order.

NOTE: Follow-Up Service Procedure revisions DO NOT include Cover Pages, Test Records and Conclusion Pages. Report revisions DO NOT include Authorization Pages, Indices, Section General Pages and Appendixes.

Please review this material and report any inaccuracies to UL's Customer Service Professionals. Contact information for all of UL's global offices can be found at <http://www.ul.com/global/eng/pages/corporate/contactus>.

If you'd like to receive updated materials FASTER, UL offers electronic access and/or delivery of this material. For more details, contact UL's Customer Service Professionals as shown above.

This material is provided on behalf of UL LLC(UL) or any authorized licensee of UL.

NBK File

UL INSPECTION CENTER 325

INDEX

USR/CNR - Indicates the switch model complies with UL61058-1 and
CAN/CSA-22.2 No.61058-1-09, for the United States and Canada.

| <u>Model No.</u> | <u>Section</u> | <u>Report Date</u> | <u>USR / CNR</u> |
|---|----------------|--------------------|------------------|
| RK1-01, RK1-03, RK1-01-3/4HP, RK1-11, RK1-12, RK1-14, RK1-15, RK1-16, RK1-21, RK1-22, RK1-23, | 1 | 2014-09-26 | USR / CNR |
| RK2-03, RK2-11, RK2-13, RK2-16, RK2-18 | 2 | 2014-09-27 | USR / CNR |
| RT2A Series | 3 | 2015-03-29 | USR / CNR |